

## **CORE BIT**

Your core bit is designed for wet use; it can also be used dry, but it will take much longer to cut. The best way to cut is to make a jig out of plywood by cutting a hole in the plywood to use as guide. The easiest is a round hole with the same diameter. You can also cut a V into one piece of plywood and another piece to press the core bit against the V-groove. Place a thin rubber band underneath surrounding the hole to be cut and clamp the plywood over it into place. Put a little soap water into the hole and start cutting. Add more soap water as needed. Remove, clean and dry the core bit after you are done.